




PDF
Complete

*Your complimentary
use period has ended.
Thank you for using
PDF Complete.*

[Click Here to upgrade to
Unlimited Pages and Expanded Features](#)


Application Note






Scan

Element	At. No.	Netto	Mass [%]	Mass Norm. [%]	Atom [%]	abs. error [%] (1 sigma)	rel. error [%] (1 sigma)
O	8	73818	6.93	80.54	96.03	0.82	11.83
Ba	56	8643	1.25	14.57	2.02	0.06	5.13
Ti	22	3943	0.42	4.89	1.95	0.04	9.37
Sum			8.61	100.00	100.00		



Scan

Element	At. No.	Netto	Mass [%]	Mass Norm. [%]	Atom [%]	abs. error [%] (1 sigma)	rel. error [%] (1 sigma)
Te	52	229322	58.32	73.92	35.73	1.74	2.98
O	8	72741	10.75	13.62	52.52	1.26	11.72
Zn	30	10405	9.82	12.45	11.74	0.37	3.75
Sum			78.89	100.00	100.00		



Scan

Element	At. No.	Netto	Mass [%]	Mass Norm. [%]	Atom [%]	abs. error [%] (1 sigma)	rel. error [%] (1 sigma)
Te	52	230708	58.47	72.52	34.90	1.74	2.98
O	8	73148	11.00	13.65	52.38	1.29	11.71
Zn	30	10405	9.81	12.16	11.42	0.37	3.75
Ba	56	2361	0.81	1.01	0.45	0.06	6.80
Ti	22	2045	0.53	0.66	0.84	0.05	8.58
Sum			80.62	100.00	100.00		



PDF
Complete

Your complimentary
use period has ended.
Thank you for using
PDF Complete.

[Click Here to upgrade to
Unlimited Pages and Expanded Features](#)

Application Note

